

Honeywell Aerospace

hereby appoints

Magnum Aviation Pvt. Ltd.

Kochi, Kerala, India

as an

Authorized Avionics Dealer

which meets the standards required to perform the following Service Categories:

- | | |
|---|--|
| 01 Silver Crown NAV/Comm/ADF/ILS/Audio/MKR Beacon Bench Repair | 15B Mark VI, Mark VIII, Mark XXII EGPWS Sys Troubleshoot to LRU |
| 01A Silver Crown Long Range NAV Bench Repair | 15C Mark VII GPWS System Troubleshoot to LRU |
| 01B Silver Crown GPS Long Range NAV Bench Repair | 15D TCAS II System Troubleshoot to LRU, ACAS |
| 01C Silver Crown GPS Long Range NAV System Install/Troubleshoot | 15E Data Recorders-SSFDR & SSCVR Sys Install/Troubleshoot to LRU |
| 02 Silver Crown Transponder/DME/RNAV Bench Repair | 20F FMS-2000 Flight Man. System, HT9000/9100-System Install/Troubleshoot to LRU |
| 02A KT70/71 Mode S Transponder Bench Repair | 30 Epic CDS/R, EFIS, Lasers, HUD-2020, Multi-Channel Satcom, Cabin Systems, Gyros, TAIS |
| 03 Primus II Radios System Install/Troubleshoot to LRU | 50 Single Engine and Light Twin NAV/COMM/Pulse |
| 03A Gold Crown NAV/Comm/ADF/ILS/Audio/MKR Beacon Bench Repair | 51 Heavy Twin and Turbine NAV/COMM/Pulse |
| 03B Gold Crown Long Range NAV Bench Repair | 52 Single Engine and Light Twin Safety Products |
| 03C Gold Crown High Frequency Bench Repair | 53 Heavy Twin and Turbine Safety Products |
| 04 Gold Crown Transponder/DME/RNAV Bench Repair | 54 Single Light Twin Autopilots |
| 04A MST 67A Mode S Transponder Bench Repair | 55 Heavy Twin Turbines Autopilots |
| 10C AA300, AM250 System Install/Troubleshoot to LRU | |
| 15A Mark V GPWS System Troubleshoot to LRU | |

The Avionics Dealership Authorization that underlies this appointment, and this certificate, are not transferable and will continue in effect until December 31, 2011 unless terminated, suspended or revoked.

Honeywell

Bill Snell

Bill Snell, *Customer Support Manager*
Aftermarket Programs
Honeywell Aerospace